

Bugreport zur letzten Leiterplatten Auflage BOR 2N7000

Beim suchen eines nicht funktionierenden Kundengerätes bin ich auf einen Herstellerfehler bei der BOR Leiterplatte der letzten Serie gestoßen. Durch die UL-Kennzeichnung des Herstellers im Layer Bottom wurde links oben in der Ecke die durchgehende Masseverbindung aufgetrennt und damit läuft die gesamte Schaltung nicht mehr.

Abhilfe schafft hier eine kleine Brücke wie im Foto gezeigt. Die Platinen habe ich beim Hersteller jetzt reklamiert und bitte hier für eventuelles suchen oder Unannehmlichkeiten um Entschuldigung. Allerdings ist der Fehler ja nicht bei mir und hat mich auch 2 Neuaufbauten und 4h Arbeit gekostet.

When looking for a malfunctioning device clients, I came across a manufacturing defect in the BOR circuit board of the last series. By the UL marking of the manufacturer in the bottom layer, the continuous ground connection was separated in the upper left corner and thus the entire circuit is no longer running.

If so, a small bridge as shown in the photo. The boards I have now reclaimed from the manufacturer and are looking here for eventuelles or Unannehmlichkeiten apologies. However, the fault's not with me and took me and two rebuilds and 4h work.

Durch UL Kennzeichnung wurde die Masse aufgetrennt
The mass was separated by labeling UL

— Brücke löten
soldering a bridge

