







P.C.B. MOUNTING HOLE DETAIL



NUT 1PC



SCHEMATIC



WASHER 1PC
t=0.8

STATUS	FREE	PULL
ON	2-3	2-1
OFF	2-1	2-3